State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code 2D2
Other Listings
Review Code Reviewer Date

Page 1 of 2 *Resource name(s) or number(assigned by recorder) 241 Lily St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 241 Lily St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0839-033

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

241 Lily Street is located on a 29.5' x 50' lot on the south side of Lily Street, between Octavia and Laguna Streets. Built in 1909, 241 Lily Street is a two-story, wood frame, two-unit multiple-family residence, designed in a modified Colonial Revival style. The rectangular-plan building is clad in shiplap wood siding and is capped by a flat roof. Its foundation is not visible from the street. The primary façade faces north and is two bays wide. The typical fenestration consists of double-hung wood windows with molded surrounds. At street level in the left bay is a small wood half-door that provides below-grade access to the basement level. The first floor features a chamfered corner and recessed porch in the left bay. This recessed porch features terrazzo stairs, a single-light glazed wood door with a flat panel surround, interior wood paneling, and two ornamental brackets. The right bay contains a broad semi-hexagonal bay window with vertical paneling, continuous wood sills, and an intermediary cornice. An intermediate cornice distinguishes the first story from the second story. The second story features two three-part windows in each bay. These windows share an entablature and cornice. The primary facade terminates in a simple entablature articulated with dentils and projecting cornice. The building appears to be in good condition.

*P3b. Resource Attributes: (list attributes and codes) HP3. Multiple family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5a. Photo



P5b. Photo: (view and date)
View from north
10/26/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1909
SF Assessors Office

*P7. Owner and Address:
Church of God in Gethsemane
D. M. Phillips CEO
240 Page St
San Francisco CA

*P8. Recorded by:
Page & Turnbull, Inc.
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
10/26/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)

P5a. Photo (cont'd)

View of entrance porch.