State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code 2D2
Other Listings
Review Code Reviewer Date

Page 1 of 1 *Resource name(s) or number (assigned by recorder) 112 Fillmore St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 112 Fillmore St. City: San Francisco Zip: 94117

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0868-019

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

112 Fillmore Street is located on a rectangular lot on the east side of Fillmore Street between Germania and Hermann Streets. Built circa 1890, 112 Fillmore Street is a 2-story, wood-frame, single-family house designed in the Queen Anne style. The rectangular-plan building, clad in shiplap siding, sits on a reinforced concrete, perimeter foundation and is capped by a hip roof. The primary façade faces west and is 2 bays wide. The right bay of the ground floor features an integrated garage, while the left bay features concrete steps and a turned post balustrade leading to the entry on the first story. The entry is set in the left bay of the first story, sheltered by a paneled porch with turned posts and a decorative roof truss. The building has a single, recessed, wooden door with transom. The right bay of the first floor features a cutaway bay window with one-over-one, double-hung, wood-sash windows with corner brackets and drop pendants. The center window is framed with paneling. The bay window is capped by a gable pediment with fish scale wood shingles, pierced verge boards, and a centered louvered vent with channeled surround. The hipped roof has asphalt shingle siding and a brick-and-metal chimney.

The building appears to be in good condition and contributes to the Hayes Valley Residential Historic District.

*P3b. Resource Attributes: (list attributes and codes) HP2: Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5a. Photo

P5b. Photo: (view and date)
View from west
8/28/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
Ca. 1890
Sanborn maps

*P7. Owner and Address:
Field George D
112 Fillmore St
San Francisco, CA

*P8. Recorded by:
Page & Turnbull, Inc.
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
8/28/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☒ None ☐ Location Map ☐ Sketch Map ☐ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)