State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code 2D2
Other Listings
Review Code Reviewer Date

Page 1 of 2 *Resource name(s) or number (assigned by recorder) 134 Haight St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 134 Haight St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0852-039; -040

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

134 Haight Street is located on a 22.3' x 84.6' lot on the north side of Haight Street, between Laguna and Octavia Streets. Built in 1895, 134 Haight Street is a 3-story, wood frame, single-family residence designed in the Italianate style. The rectangular-plan building is clad in horizontal drop wood siding and capped by a flat roof. Its foundation is not visible from the street. The primary façade faces south and is two bays wide. In the right bay of the ground floor is a below-grade, multi-panel garage door. The first floor features a gated, recessed entry porch in the left bay, which is approached by terrazzo steps. This porch is demarcated by an entablature supported by fluted columns with Corinthian capitals. The entrance is lined with wood paneling and has a glazed wood door with a molded surround, sidelights, and a transom. On the second floor, the left bay features a single window with an ornamental pediment. A two-story box bay window fills the right bay of the first and second floors. The first floor of the bay window is capped by an entablature featuring a paneled frieze, dentils, and modillions, and a broken triangular pediment. The second floor of the bay window is distinguished by an ornate entablature adorned with scrollwork, cartouches, and shell motifs.

*P3b. Resource Attributes: (list attributes and codes) HP2. Single family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5a. Photo



P5b. Photo: (view and date)
View from south
10/26/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1895
SF Assessors Office

*P7. Owner and Address:
Encinas Veronica E
134 Haight St #A
San Francisco, CA 94102

*P8. Recorded by:
Page & Turnbull, Inc. (CM)
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
10/26/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)

***P3a. Description: (cont'd)**
The fenestration on this façade is composed of arched, double-hung wood-sash windows with molded surrounds. The primary facade terminates in a heavy entablature with sculpted panels, dentils, large brackets and a deep-projecting cornice. Above, the parapet wall is lined with engaged balusters. A rooftop addition is partially visible from the street. The building appears to be in good condition.

P5a. Photo (cont'd)


Detail of entrance.

Detail of bay window.