State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code 2D
Other Listings
Review Code Reviewer Date

Page 1 of 2 *Resource name(s) or number (assigned by recorder) 386-388 Lily St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 386-388 Lily St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0840-014A

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

386-388 Lily Street is located on a 25' x 43' lot on the north side of Lily Street, between Buchanan and Laguna Streets. Built circa 1897, 386-388 Lily Street is a two-story, wood frame, two-unit multiple-family residential building that has been substantially altered. The rectangular-plan building, clad in broad horizontal drop wood siding, sits on a reinforced concrete perimeter foundation and is capped by a flat roof. The primary façade faces south and is two bays wide. The left bay of the first floor features a gated, recessed porch with a molded surround, which contains two glazed wood doors with transoms. The right bay of the first floor features a rectangular small window and a secondary entrance with a metal security gate. The upper floor is characterized by a double-hung wood-sash window with a flat-panel surround in the left bay, and a box bay window in the right bay. On the upper portion of the second floor is a broad flat-panel intermediary cornice with an applied central ornament featuring a griffin and the date "1897." The primary facade terminates in parapet wall distinguished by a wide unadorned entablature, dentil molding, and a box cornice. The building appears to be in good condition.

*P3b. Resource Attributes: (list attributes and codes) HP3. Multiple family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other

P5a. Photo

P5b. Photo: (view and date)
View from south
10/27/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1900; rev. ca. 1897
SF Assessor; Sanborn Maps

*P7. Owner and Address:
Michael Willemsen
485 Summit View Dr
Arnold, CA 95223

*P8. Recorded by:
Page & Turnbull, Inc. (CM)
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
10/27/2006

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)

P5a. Photo (cont'd)

Detail of entrance.

Detail of ornament on second story intermediary cornice.