State of California — The Resources Agency
DEPARTMENT OF PARKS AND RECREATION

PRIMARY RECORD

Primary #
HRI #
Trinomial
NRHP Status Code
Other Listings
Review Code Reviewer Date

Page 1 of 2 *Resource name(s) or number (assigned by recorder) 64-66 Laussat St.

P1. Other Identifier:

*P2. Location: ☐ Not for Publication ☒ Unrestricted *a. County: San Francisco

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad: San Francisco North, Calif. Date: 1956 (rev. 1973)

*c. Address: 64-66 Laussat St. City: San Francisco Zip: 94102

d. UTM: Zone: 10 mE/ mN (G.P.S.)

e. Other Locational Data: Assessor's Parcel Number (Map, Block, Lot): 0858022A

*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries.)

64-66 Laussat Street is located on a 25' x 39.08' lot on the north side of Laussat Street. It is a 2-story, wood-frame residential building designed in the Classical Revival style. The rectangular-plan building sits on a high foundation that is covered with wood shiplap siding. A wood water table divides this foundation skirting from the walls above, which are clad in narrow wood shiplap siding. The building is capped by a flat roof with a high parapet across the front. The primary window type is a one-over-one, double-hung, wood sash with lambs tongues. These windows can be found, paired, on the west side of the front elevation, on a bay window on the west side of the second-story level, and as a single window on the east side of the second story level, above the entry. The primary entry is located at the east side of the front façade and consists of two glazed wood panel doors within an inset vestibule. The opening of the vestibule is flanked by paneled trim and topped by a hood with an egg-and-dart molding. The windows on the front façade are surrounded by simple trim and projecting hoods; wall panels are located below the windows in the second story bay window. The entire façade is surmounted by a prominent entablature, consisting of a narrow frieze, egg-and-dart and dentil moldings and an overhanging cornice. The secondary elevations are clad in wide wood lap siding. The building appears to be in good condition.

*P3b. Resource Attributes: (list attributes and codes) HP3: Multiple family property

*P4. Resources Present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other



P5b. Photo: (view and date)
View from southeast
10/25/2006

*P6. Date Constructed/Age and Sources: ☒ Historic
1900
SF Assessor

*P7. Owner and Address:
1116 Fulton Street
San Francisco, CA. 94117

*P8. Recorded by:
Page & Turnbull, Inc.
724 Pine Street
San Francisco, CA 94108

*P9. Date Recorded:
8/17/2007

*P10. Survey Type:
Reconnaissance

*P11. Report Citation: (Cite survey report and other sources, or enter "none") None

*Attachments: ☐ None ☐ Location Map ☐ Sketch Map ☒ Continuation Sheet ☐ Building, Structure, and Object Record ☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record ☐ Artifact Record ☐ Photograph Record ☐ Other (list)

Page 2 **of** 2 ***Resource Name or #** (Assigned by recorder) 64-66 Laussat St.

***Recorded by:** Page & Turnbull ***Date** 8/17/2006 ☒ Continuation ☐ Update



Detail of second story and roofline.

Detail of primary entry.